ER. BINDESHWAR PANDIT

B.E(Civil), M.E.FIV, MIE

MCD Licensed Engineer E-00099

MCD Structural Engineer S.E-26 Govt. Regd. Valuer U/S 34 (AB) of 1957

Income Tax

Structural Designer Chartered Engineer Registered Valuer IBBI

264, D.A Flat, Phase-IV Nimri Colony, Ashok Vihar

Delhi-110052

Off: 5, Sanjay Nagar, Near NKS hospital Delhi-7

Mobile No.-9810988628, 9821368002 E-mail ID:-bpandit2013@gmail.com

Ref.No.15/SSC/DPSSL/GURUGRAM/2023 Date:-19.09.2023

STRUCTURE STABILITY CERTIFICATE

Address of property: Delhi Public School, Block-B, Sushant Lok-1,

Gurugram (Haryana), 122009

Name of owner

: M/s Trinity Wisdom Academy Pvt. Ltd.

The building property is bounded as under

East

: 12.00 M Wide Road

West

: 12.00 M Wide Road

North

: Plot No.B/431A to 452A

South

: 12.00 M Wide Road

I had visually inspected the above cited School building on dated 18.09.2023 at 2:30 PM on the request of above said owner. The building contains Block-A and Block-B. Both the block consist of Basement, Ground Floor, First Floor Second Floor and Third Floor with Terrace. The building structure is RCC framed structure containing Column, Beam and Slab with 345mm and 230mm thick brick wall. The building structure of Block-A has been constructed in the year 2010 and Block-B in 2012. inspection I observed that there is no deflection, Cracks, Crippling and bending in RCC structure. As on the date of inspection I found that the physical condition of structure of the building is good and well maintained.

The above mentioned existing building satisfies the safety requirement and the structural design including safety from natural hazards based on soil conditions has been duly incorporated in the design and construction.

In my view the above said building is safe and sound.

(Bindeshwar Pandit) Structure Engineer

BINDESHWAR PANDIT MCD Structural Engineer License No.SE-26 264, D.A. Flats, Nimri Colony Ph-IV, Ashok Vihar, Delhi-52